telestream

PRISM

SDI / IP Waveform Monitor

Release Notes

This document supports firmware version 3.3.3

Contact Telestream
Telestream LLC
848 Gold Flat Road
Nevada City, CA 95959
USA

For product information, sales, service, and technical support:
Worldwide, visit www.telestream.net/telestream-support/video/support.htm to find contacts in your area.

Release notes

This document describes new features, fixes, and improvements of firmware version 3.3.3 for the PRISM SDI / IP Waveform Monitor.

Compatible Products

Upgrades   The following 25G products are compatible with this release:

- MPI and MPX that have been upgraded to 25G

- MPI2-10 and MPX2-10 that have been upgraded to 25G

- MPI2-25 and MPX2-25

- MPS-100/200/300

- MPD-100/200/300

NOTE: This release is not compatible with 10G systems:

- MPI and MPX without 25G upgrade

- MPI2-10 and MPX2-10 without 25G upgrade

Downgrades   Downgrading from version 3.x to 2.x is not allowed for the following products due to the hardware configuration:

- MPI2-25 with serial number starting at S010564

- MPX2-25 with serial number starting at S010386

- All MPS/MPD products

Downgrading to a version earlier than v3.3.3 is not allowed for the following products due to the hardware configuration:

- MPI2-25 and MPX2-25 with serial number starting at S011000

- MPI2-10, MPX2-10, MPI, and MPX that have been upgraded to 25G and have Input Board Type "MMC25 rev A.3" or later (see Settings > Utilities > Version)

New features

There are no new features or resolved defects in this release. This release is intended for products that have the following hardware platform changes:

- MPI2-25 and MPX2-25 with serial number starting at S011000

- MPI2-10, MPX2-10, MPI, and MPX that have been upgraded to 25G and have Input Board Type "MMC25 rev A.3" or later (see Settings > Utilities > Version)